

FIG. 1

INFLUENCE OF SLOPE ANGLE  
ON REVEGETATION

0001



UTAH DIV. OF OIL, GAS AND MINING  
FEBRUARY 1992

FIG. 2

EXAMPLE OF PIT HIGHWALLS  
DESIGNED TO MEET THE 45°  
REQUIREMENT

UTAH DIV. OF OIL, GAS AND MINING  
FEBRUARY 1992



William Almas  
Environmental Coordinator  
Energy Fuels Nuclear  
One Tabor Center, Suite 2500  
1200 Seventeenth Street  
Denver, Colorado 80202

Roy Benson  
Geneva Steel  
P. O. Box 20-B, RFD #1  
Santaquin, Utah 84655

Mark F. Lindsey  
Native Asphalt Company  
136 South Temple  
University Club Building, Suite 1750  
Salt Lake City, Utah 84111

Glen Eurick  
Environmental and Occupational  
Health Coordinator  
Barrick Mercur Gold Mines, Inc.  
P. O. Box 838  
Tooele, Utah 84074

Fred Fox, Director  
Environmental Affairs  
Kennecott Utah Copper  
P. O. Box 525  
Bingham Canyon, Utah 84006-0525

Jim Smith  
Tenneco Minerals  
P. O. Box 2650  
St. George, Utah 84770

Jack E. Christensen, President  
Utah Mining Association  
Kearns Building  
136 South Main  
Salt Lake City, Utah 84101

Teresa E. McParland  
Branch of Solid Minerals  
Bureau of Land Management  
P. O. Box 45155  
Salt Lake City, Utah 84145-0155

Robert Sykes  
Intermountain Region  
Forest Service  
Federal Building  
324 25th Street  
Ogden, Utah 84401

Scott Endicott  
Sierra Club  
865 Belmont  
Salt Lake City, Utah 84105

Wayne Mortinson  
Utah Audobon Society  
1181 1st Avenue  
Salt Lake City, Utah 84103